


UPR Billet Oil Drain Plug Installation



Remove the factory drain plug by rotating counter clockwise.



Rotate the UPR Billet drain plug clockwise until the retaining tabs are FULLY SEATED in the oil pan retainer grooves.

Caution: It is best to perform an engine oil service when the engine has been allowed to cool. The UPR Billet Drain Plug is in direct contact with engine oil and WILL BE HOT to the touch if the engine is still at operating temperature. Use Gloves and Protective Gear when servicing the vehicle. It is important to clean and inspect the Billet Oil Drain Plug magnet and O ring. Replace O ring as needed. If the retaining tabs on the UPR Billet Drain Plug become loose or damaged, do not reinstall until they are repaired properly or the drain plug is replaced. Applying light pressure to bend them back into shape is acceptable as long as the retaining tabs properly engage the retaining groove in the oil pan.



Product Liability Statement: The purchase of the product, manufactured by UPR Products Inc. completes an agreement between UPR Products Inc. and the customer. UPR Products Inc. assumes no liability for damages or injury incurred by the buyer of this product. The buyer has complete responsibility for the installation, use and upkeep of this product.